



NOTES

- 1. RED WIRE TO SIDE OF CONNECTOR WITH SINGLE RIB.
- 2. ADJUST WIRES BEFORE SHRINKING OUTER SLEEVE.
- 3. BLACK WIRE TO PASS UNDER OUTER SLEEVE.
- PT WIRES MUST BE WELDED INTO POSITIONS SHOWN, AS DETAILED IN RELATIVE SAFT WORKMANSHIP STANDARD AND PROCESS PLANNING SHEET.

Note :

- 1. Polarité spéciale du connecteur
Cable rouge coté connecteur avec simple nervure
- 2. Ajuster les cables avant rétraction de la gaine chaussette.
- 3. Le cable noir doit passer sous la gaine chaussette .
- 4. Les 2 cables doivent être soudés selon les positions montrées suivant le savoir faire et les fiches d'instruction.

2 VTD037 C FORM WITH BACK PLATE 7030-0628.

WITHOUT OUR PERMISSION, THIS DRAWING MAY NOT BE REPRODUCED OR MADE AVAILABLE TO THIRD PARTIES.

MATERIAL: SEE PARTS LIST					REFER:					
FINISH:					SCALE: DIAGRAMMATIC		MASS:		DATE: 04.10.89	
TOLERANCE:					APPROVED:		CHECKED:		DRAWN: ARP	
ISS	DATE	AUTHOR	MODIFICATION	DCN	CR			SAFT NIFE LTD STATION ROAD HAMPTON MIDDLESEX, TW12 2BY TEL: 00 44 181 9797755 FAX: 00 44 181 7830494		ISS
B	10.03.98	EB	Etait sans référence client		110398JPB	0757-302-220		Réf. 787578		B
A	5.2.98	CM	WAS WITHOUT S.Y. PART NUMBER	98008	5.2.98 JPB					A
1	4.10.89	ARP	ISSUED							1